Fiber Coupled Array FCA600C030

- 600 μm Fiber Diameter, 0.2 NA
- · Detachable SMA Fiber
- 30W Output Power



OPTICAL CHARACTERISTICS

PARAMETER	CONDITIONS	MIN	TYP	MAX	UNITS
CW Power Output	25°C Heat Sink	30			W
Operating Current ⁽²⁾	30W at 25°C Heat Sink		39	44	Α
Threshold Current	25°C Heat Sink		7.0	10	Α
Center Wavelength	30W at 25°C Heat Sink		808	/	nm
Wavelength Tolerance	30W at 25°C Heat Sink		± 3	/	nm
Spectral Width FWHM	30W at 25°C Heat Sink		3.0	- <u>-</u> 4	nm
Wavelength Shift			0.25	1 y	nm/°C

ELECTRICAL CHARACTERISTICS

PARAMETER	CONDITIONS	MIN	TYP	MAX	UNITS
Series Resistance	25°C Heat Sink	,	0.006	0.012	ohms
Operating Voltage	25°C Heat Sink		1.9	2.1	V

ABSOLUTE MAXIMUM RATINGS


PARAMETER	CONDITIONS		
Forward Current	50A		
Reverse Current	25μA		
Reverse Voltage	0V		
Operating Temperature Range (3)	15°C or to 30°C		
Storage Temperature Range	-20°C to 60°C		


NOTES


- (1) These specifications apply for operation at 808nm. Other wavelengths available upon request.
- (2) Beginning of life
- (3) A dry nitrogen environment should be provided by the user when storing and operating at temperatures below ambient point.



MECHANICAL CHARACTERISTICS








Copyright © 2005 Northrop Grumman Cutting Edge Optronics All Rights Reserved. Northrop Grumman Cutting Edge Optronics reserves the right to change product design and specifications at any time without notice.

No license is granted by implication or otherwise under any patents or patent rights of Northrop Grumman Cutting Edge Optronics or others.

No responsibility is assumed for the use of these products, nor for any infringement on the rights of others resulting from the use of these products.

Information contained herein is believed to be reliable and accurate

This Product is covered by one or more of the following Patents: 5,898,211 5,985,684 5,913,108 6,310,900 Other US and Foreign Patents Pending.





body is exposed to the beam. The eye is extremely sensitive to the infrared radiation and therefore, proper eyewear must be worn at all times. Use of optical instruments with these products may increase

eve hazard. Always were proper eve protection when operating.

NORTHROP GRUMMAN